

Vehicle Check - Japan Auction Sheet Report

Report requested on 05/09/2022, 11:17 pm

Reference Number: XXXXXXXXXX

Vehicle Details Date: 2020-10-14, Lot #2520

Chassis No.	XXXXXXXXXX	Colour	SILVER
Manufactured Year	2017	Frame	NSP141
Make	TOYOTA	Specs	G
Model	SPADE	Grade	R
Mileage	17 000 km	Inspection Date	<i>unknown</i>
Displacement	1,500 cc	Options	Air conditioning with automatic control (climate control)
Transmission	Automatic Transmission	Status	Unsold

AUCTION DETAILS

Auction House	Auction Date	Lot No.
JU Ibaraki	2020-10-14	2520

MARKET PRICE IN JAPAN

Start Price (¥)

End Price (¥)

80,000

338,000

PHOTOS AND AUCTION SHEETS

出品番号 2520	初度登録年月 H29 4月	車名・グレード スパイト G	2WD 4WD	評価点 R
型式 [Redacted]	排気量 1500cc	ドア形状 4W	定員 5人	ディーラー・並行 モデル年式 kg
車歴 自家用・()	シート AT	セールスポイント (正常に機能するものに限ります) ・走行1.6万キロ!! ・ナビ テレビ Bluetooth オート ・バックカメラ ・社外フィルム ・ETC		
車検 年 月(日)	冷房 AAC	整備品 (純正品に限りをつけてください) PS PW ABS ETC AW SR FE TV 本革 無		
走行 1万6千829 km	燃料 軽油	新車保証書 無		
色 シルバー	色替 ?	R券 9,340 円 名変期限 月 日		
注意事項申告欄 (不具合内容等は具体的に記入して下さい) ルームミラーニング済!! ①保 ②取 コーナセンサー ③専用ナビ付 修復歴 有 [箇所]				
検査員 FW キズ・飛石・ヒビ割・リペア跡・×要 記入欄 内装 キズ・汚損・コゲ・穴・破損・キレ・破損				
<ul style="list-style-type: none"> 左Fヒーター 修正 XX 右Fヒーター 追加 修正 ナビコンソール スク 右Fセンサー アジャスト 修正 右センサーヒーター キズ口 スチール W2 コンソールプレート 欠 				
車台番号	[Redacted]			
登録番号	[Redacted]			
<p>A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済</p> <p>型式指定番号 18119 類別区分番号 0013</p> <p>車庫証明用 長さ 399 cm 幅 169 cm 高さ 169 cm</p>				









Vehicle Details

Date: 2020-09-24, Lot #87721

Chassis No.	██████████	Colour	SILVER
Manufactured Year	2017	Frame	NSP141
Make	TOYOTA	Specs	G
Model	SPADE	Grade	R
Mileage	17 000 km	Inspection Date	<i>unknown</i>
Displacement	1,500 cc	Options	
Transmission	Automatic Transmission	Status	Available

AUCTION DETAILS

Auction House	Auction Date	Lot No.
USS Tokyo	2020-09-24	87721

MARKET PRICE IN JAPAN

Start Price (¥)	End Price (¥)
100,000	<i>unknown</i>

PHOTOS AND AUCTION SHEETS

SAMPLE


ロープラコーナー

87721	車歴 (自家用以外は記入)	排気量	型式	評価点
	初年度登録年月	車名	グレード	
	29/4月	スピード	G	R
			2WD 4WD	B

車検	年	月	シフト	SR	純AW	PS	PW
			AT	カワ	TV	ナビ	I7B
走行	16,822	Km	冷房	セールスポイント			
外元色	色輪	カラー	無	整備と販売			
燃料	ソリノ	軽油	無	ETC. ナビ			
型式	輸入区分	ハンドル	名義変更期間				
ディーラー	並行	左・右	月 日				
リサイクル	9340	円	登録地				
預託金			車台				
○注意事項 (修理・不具合箇所および状態等)			シリアル				

○検査員報告 (USS使用欄) 各社計

左ハンドル 2007 左ハンドル)
 コナセ不良 左ハンドル)
 コナセ不良 左ハンドル)
 左ハンドル不良 左ハンドル不良)
 左ハンドル不良 左ハンドル不良)
 左ハンドル不良 左ハンドル不良)
 左ハンドル不良 左ハンドル不良)
 左ハンドル不良 左ハンドル不良)



台内寸約 X X (cm)





Vehicle Details

Date: 2020-07-02, Lot #80400

Chassis No.	██████████	Colour	SILVER
Manufactured Year	2017	Frame	NSP141
Make	TOYOTA	Specs	G
Model	SPADE	Grade	***
Mileage	17 000 km	Inspection Date	unknown
Displacement	1,500 cc	Options	
Transmission	Automatic Transmission	Status	Available

AUCTION DETAILS

Auction House	Auction Date	Lot No.
USS Tokyo	2020-07-02	80400

MARKET PRICE IN JAPAN

Start Price (¥)

End Price (¥)


unknown

unknown

PHOTOS AND AUCTION SHEETS

事故現状車コーナー

80400	車種 (自家用以外は記入)	排気量	型式	内装
		1500		
	初年度登録年月	車名	駆動方式	グレード
	29/4月	スパイト		G
			2WD 4WD	
車検	年	月	シフト	AT
走行	16,739	Km	冷機	AAC
外色	シルバー	色	有	無
燃料	ガソリン	内装色	無効	
型式	ディーラー	ハンドル		
リサイクル	9,340	円	登録	
注意事項 (事故・不具合箇所および状態等)			車台	
自走可能			シリアル	
エアバッグ				
パワウィンドウ				
検査員報告 (USS使用欄)				
F. 左右面現状				
リフト使用				
台内寸約	X	X	(cm)	
長さ	cm	幅	高さ	cm
				スペース





GLOSSARY

¹ **Chassis number** – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

How to read Auction Grades and Inspection Reports

Auction grade is the overall assessment of a car given by the Japanese car auction house's inspectors. There are currently over 115 auction house locations that test and provide the auction grades base on the general condition of the car or vehicle. Though different houses have various methods of determining each grade; the systems are likely similar and giving the almost same result.

The grades are usually showed as numbers or letters for the overall grade based on the visible and mechanical condition. Some auctions use Letter –A, B, C, D or E to describe the exterior and/or interior condition of the car, in addition to the overall grade, where A>B>C>D>E.

Overall Grade

- **Grade 6 or higher or "S"** : Considered as brand new, less than 12 months of old, and/or with a mileage under 10,000 km.
- **Grade 5** : As good as new, with exceptionally low mileage.

- **Grade 4.5** : Very slightly used, mileage of up to **100,000 km**.
- **Grade 4** : Used condition, pre-loved but well looked after with very light blemishes.
- **Grade 3.5** : You can find noticeable scratches, dents, rust or corrosion (rare). Inside the vehicle often appear tears, cigarette holes, stains.
- **Grade 3** : Visible huge scratches, dents, paint stains, rust and corrosion. Interior full of tears, cigarette holes or food stains.
- **Grade 2** : Poor condition, usually featuring unrepaired accident damage or corrosion, but the car is functional.
- **Grade 1** : Modified or disaster cars like flood.
- **Grade R or 0** : Accident history/repaired. Repaired parts are mostly mentioned in auction sheet.
- **Grade RA** : Minor accident cars that have been fully repaired.
- **Grade RB** : Slightly more serious than RA.
- **Grade RC** : Pillar or frame has been changed/repaired.
- **Grade R2** : Accident history and mostly rust or corrosion issue.
- **Grade * or ***** : Non running car, needed a forklift to be moved, Major accident.

Interior or Exterior grade

Used car auction grade for the interior/exterior is as follows:

Interior Grading:


- **A** – New vehicle's condition.
- **B** – Car is in good condition, the interior looks nice and tidy.
- **C** – Small food's stains or cigarette's holes could be found inside the car.
- **D** – Inner vehicle consists of cigarette's mark, stains, tears or smell.
- **E** – Interior of the car is in bad condition. Grade E means all mentioned above and even worse.

Exterior Grading:

- **A** – A pristine exterior condition.
- **B** – Some small scratches up to 15cm could be found.
- **C** – Scratches up to 30 cm or dents could be seen.
- **D** – Visible scratches, rust or corrosion are detected.
- **E** – The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty.

For advanced-level buyers

If an auction sheet is available, inspection markings (image below) indicated by the inspectors can tell you more about the vehicles condition.



If the Auction Inspection Sheet is available, look for these marks & understand the vehicles condition.

- A1 Small scratch
- A2 Scratch
- A3 Big scratch
- B1 Small dent with scratch (size like a thumb)
- B2 Dent with scratch (size like flat of the hand)
- B3 Big Dent with scratch (size like elbow)
- C1 Corrosion
- C2 Heavy corrosion
- E1 Few Dimples
- E2 Several Dimples
- E3 Many Dimples
- G Stone chip in glass
- H Faded paint
- P Marked paint

R	Repaired windshield crack
RX	Repaired windshield crack (must be replaced)
S1	Rust
S2	Heavy Rust
U1	Small dent
U2	Dent
U3	Big dent
W1	Hardly detectable repair mark/wave (hardly detectable)
W2	Repair mark/wave
W3	Visible repair mark/wave (needs to be repainted)
X	Windshield crack (must be replaced)
XX	Replaced
X1	Small windshield crack (approximately 1cm)
Y1	Small crack or hole
Y2	Crack or hole
Y3	Big crack or hole

ACCESS YOUR REPORT ONLINE

A copy of your report can be accessed anytime via your [Profile](#).

NEED HELP WITH READING THE REPORT?

Visit our website for frequently asked questions and our guide to help you better understand your report.

- [FAQs](#)

GENERAL DISCLAIMERS

This report has been supplied on the [Terms and Conditions](#) set out on the CTOS website.

The data used to compile this report has been sourced from various independent and Government sources, as a result CTOS can accept no responsibility for the accuracy or completeness of information.