

Powered by OTØFACTS

CTOS Vehicle Check - Basic Check

VIN: MR053REH3045*****

Report generated on 25/10/2024, 01:41 pm

Reference number: P9bGvwq2

Vehicle Information



* Image for illustration purposes only

VIN ¹	MR053REH3045****		
Make	TOYOTA		
Model	COROLLA		

Basic Claims

✓ Stolen - No Claims Reported.

✓ Total Loss (Structural Damage) - No Claims Reported.

Insurer History

No	Insurer	Type of Cover	Policy Number	Policy Period
1.	Amgeneral insurance berhad	Comprehensive	3BW86****	08 May 2023 - 07 May 2024
2.	Amgeneral insurance berhad	Comprehensive	3DW83****	20 Feb 2023 - 19 Feb 2024
3.	ALLIANZ GENERAL INSURANCE COMPANY (MALAYSIA) BERHAD	Comprehensive	20VPJ0010****	23 Jul 2021 - 22 Jul 2022

GLOSSARY

- This report is only based on information supplied and available to OTOFACTS as of 25 Oct 2024 (Asia/Kuala Lumpur).
- Malaysian databases are updated frequently. Please make sure you have the latest report.
- The absence of accident claims **DOES NOT** necessarily mean the vehicle is accident-free.

NEED HELP WITH READING THE REPORT?

Visit our website for frequently asked questions and our guide to help you better understand your report.

FAQs

GENERAL DISCLAIMERS

This report has been supplied on the Terms and Conditions set out on the CTOS website.

The data used to compile this report has been sourced from various independent and government sources, as a result CTOS can accept no responsibility for the accuracy or completeness of information.

¹ Chassis number / VIN - A unique identification number assigned to a vehicle by the manufacturer. It is usually found on the vehicle's dashboard, door frame, or engine block.